


Rändelmutter hohe Form



d	dk	ds	h	k
M 2	9	4,5	5,3	2
M 2,5	11	5	6,5	2,5
M 3	12	6	7,5	2,5
M 4	16	8	9,5	3,5
M 5	20	10	11,5	4
M 6	24	12	15	5
M 8	30	16	18	6
M 10	36	20	23	8