


Rändelmutter niedrige Form



d	dk	ds	h	k
M 2	9	4,5	2,5	2
M 2,5	11	5	3	2,5
M 3	12	6	3	2,5
M 4	16	8	4	3,5
M 5	20	10	5	4
M 6	24	12	6	5
M 8	30	16	8	6
M 10	36	20	10	8