


DIN 966 (ISO 7047)

Linsenschraube mit Kreuzschlitz

(H = Phillipsdrive , Z = Pozidrive)



| d | M2 | M2,5 | M3 | M4 | M5 | M6 | M8 |
|-----|-----|------|------|-----|------|-----|------|
| dk | 3,8 | 4,7 | 5,6 | 7,5 | 9,2 | 11 | 14,5 |
| k | 1,2 | 1,5 | 1,65 | 2,7 | 2,5 | 3 | 4 |
| f | 0,5 | 0,6 | 0,75 | 1 | 1,25 | 1,5 | 2 |
| l | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 8 | | | | | | | |
| 10 | | | | | | | |
| 12 | | | | | | | |
| 14 | | | | | | | |
| 16 | | | | | | | |
| 18 | | | | | | | |
| 20 | | | | | | | |
| 22 | | | | | | | |
| 25 | | | | | | | |
| 30 | | | | | | | |
| 35 | | | | | | | |
| 40 | | | | | | | |
| 45 | | | | | | | |
| 50 | | | | | | | |
| 60 | | | | | | | |
| 70 | | | | | | | |
| 80 | | | | | | | |
| 90 | | | | | | | |
| 100 | | | | | | | |